


FIG. 1 PRIOR ART

10'








FIG. 3 PRIOR ART

10a'




FIG. 4 PRIOR ART




FIG. 5

A Secretaria de la companya del companya del companya de la compan

المنيد المراجع




FIG. 6A




FIG. 6B

100







FIG. 7








FREQUENCY IN HZ BODE RESPONSE WITH TORQUE DISTURBANCE AT HDA ACTUATOR

1.5








FIG. 12








FIG. 15

0**5**1 1 - 1 1;




FIG. 16